



HIFLO DIESEL PRODUCTS
FACTORY 4, 12-14 REGAL DVE
SPRINGVALE, VICTORIA, 3171
AUSTRALIA
PH: (03) 9547 9222
FAX: (03) 9546 3279
FREECALL: 1800 817 006
EMAIL: hiflo@hiflo.com.au
WEBSITE: www.hiflo.com.au

HKT GLOW PLUGS CROSS REFERENCE CHART

Hiflo has a large range of high quality HKT diesel glow plugs to suit popular 4WD's and light commercial vehicles.

Item #	Manufacturer	Model	Engine	Plug Voltage
G-CPH-03	NISSAN	NAVARA	QD32	11.0
C-CPH-04	NISSAN	PATROL GU	RD28 ETI	11.0
G-CPH-05	MITSHUBISHI	PAJERO/TRITON	4M40	11.0
G-CPH-07	MITSHUBISHI	PAJERO/DELICA	4D56	11.0
G-CPH-22	TOYOTA	HILUX, PRADO	1KZ-TE	11.0
G-CPH-70	NISSAN	PATROL GQ	RD28 [cyl 1,2,3]	6.5
G-CPH-71	NISSAN	PATROL GQ	RD28 [cyl 4,5,6]	6.5
G-CPH-73	NISSAN	PATROL GU	ZD30	11.0
G-PIH-172	HOLDEN	JACKAROO	4JX1	11.0
G-PMH-164	MITSHUBISHI	DELICA	4D56	11.0
G-PMH-165	MITSHUBISHI	DELICA	4M40	11.0
G-PMH-168	MITSHUBISHI	PAJERO	4M41	11.0
G-PNH-123	NISSAN	NAVARA	SD23	11.0
G-PNH-135	NISSAN	PATROL GQ	TD42	11.0
G-PNH-138	NISSAN	PATROL GU	TD42T	11.0
G-PTH-140	TOYOTA	HILUX, HIACE	2L	7.0
G-PTH-144	TOYOTA	HILUX	L	11.0
G-PTH-145	TOYOTA	LANDCRUISER	B, 3B	10.5
G-PTH-146	TOYOTA	LANDCRUISER	2H	6.0
G-PTH-151	TOYOTA	HILUX, HIACE	3L	11.0
G-PTH-152	TOYOTA	LANDCRUISER	2H, 1HZ, 1HDT	11.0
G-PTH-155	TOYOTA	HILUX	5L	11.0
G-PZH-33	MAZDA/FORD	BRAVO/COURIER	R2	10.5
G-PZH-39	MAZDA/FORD	BRAVO/COURIER	WL-T	11.0

One of the main reasons an automotive diesel engine can be hard to start is faulty glow plugs. Not all the glow plugs have to be bad before the engine gets hard to start.

Common signs of faulty glow plugs:

- Difficulty starting, especially with cooler air temperatures.
- Rough idle & running when engine is cold, with lots of white/grey smoke smelling of unburnt diesel, which clears as engine temperature increases.



For other vehicle applications, or for more information on our range of glow plugs or other products, please call us freecall on 1800 817 006